



COMMUNITY DEVELOPMENT DEPARTMENT

Building Inspection Division

221 West Pine St./PO Box 3006, Lodi, CA 95241-1910

(209) 333-6714

Seismic Upgrade for URM Buildings

Policy and Procedure-B

[January] 2008

POLICY FOR SEISMIC UPGRADE OF UNREINFORCED MASONRY BUILDINGS

A seismic upgrade to an existing un-reinforced (URM) building will be required when one of the following conditions exist:

1. The URM building is in obvious structural failure. Structural deficiencies such as listing walls, large cracks or roof and floor deflection would be examples of this condition. Unsafe parapets may be required separately if there are no other problems related to the structure or not covered in items 2 and 3 below.
2. A change of occupancy to a more restrictive use. A change to an A occupancy (assembly) or an H occupancy (hazardous) from an office or warehouse are examples. The 2007 California Building Code, Chapter 34, shall be used as a guideline.
1. Remodeling or rehabilitation that involves structurally altering an existing URM building. Enlarging openings in existing bearing walls, floors, or roofs are examples.

The seismic upgrade shall be designed by a licensed architect or registered engineer using the 2007 California Building Code, Section 3413A as a minimum standard.