

**Lodi Citizen's Monitoring - Lodi, California**



**RAINFALL: (New Season Begins- 7-01-16)**

**last rain: 2/22/2017**

**Day's rainfall: .01**

**Month to date: 7.37"**

**2016-2017: Season total: 27.48"**

**Weather:** (14.625C/58.325F)

**VISUAL OBSERVATIONS-Light breeze/windy/clear and sunny**

DATE	SITE	ODOR	ALGAE	FOAM	TURBID.	FLOW	OIL	LITTER	COLOR	INVASIVE SPECIES
28-Feb-17	site 1	None	None	None	Clear	High	None	None	None	None
	site 2									
	site 5									
	site 7	None	None	None	Clear	High	None	None	None	None
	site 7A									
	site 8	None	None	None	Clear	Medium	None	Light(<5pcs)	None	None
	site 9									
	site 9C	None	None	None	Clear	High	None	None	None	None

**River Water Level: Camanche releases 4973cfs/ Pardee 3120cfs.**

**Monitored by:**

**Tokay HS** Sites # 1- Vacarezza Private Property-Tokay- (Starr- Erendira Terrazas, Keri Wyatt, Kristen Fukunaga  
 Site #2- Gritsch Private Property- Tokay- not monitored- peninsula under water  
 Site # 5- 1050 N Lincoln- Not monitored

**Heritage School** Site # 7- Gazebo- Heritage- (Jacinto/Juran)- A. Arong, A. Villanuva, C. Martinez, P. Lopez, J. Juarex  
 Site # 7-A- East end (S/o SD) Lake-

**Reese School** Site # 8- West side Lodi Lake, near outfall- at shore-Reese (Martinez)- T. Flores, K. Carson, T. Copeland, C. Locke  
 Site # 9- Above WID Bridge and Dam- Not monitored  
 Site # 9-A- Below Bridge- Not monitored  
 Site # 9-B- Surface Water Treatment Facility- Sed Basin Sampler

**Tokay HS** Site # 9C- WID office at river- Tokay- Same as Site # 1.

Test Site	Date	Time	pH	Water Temperature		Dissolved Oxygen mg/L	Turbidity NTU	EC Conduct. uS	Nitrate, as mg/L Nitrogen	Remarks
				10.7 C	51.3 F					
Site #1 River before City orm System inlets	2/28/17	15:29	8.4	10.7 C	51.3 F	12.2	11.00 ntu	40	0	A lot of wood ducks. Water level high.
Site # 2 River near Casa de Lodi			B	A	A	A	B	A	A	NOT MONITORED. PENINSULA FLOODED.
Site # 5 River at 1050 N Lincoln										
Site # 7 N/O Lodi Lake	2/28/17	15:18	7.8	10.2 C	50.4 F	11.6	14.3 ntu	50	0	We went to the river to check the water. Ducks, geese, flow very fast.
Site # 8 Lake Park- west lake	2/28/17	15:20	8	10.5 C	50.9 F	11.3	13.7 ntu	50	0	Dog playing in the water. Man fishing.
Site # 9 River- Upstream of dam										
Site # 9A River below WID below bridge										
Site # 9C e, near river take out canal	2/28/17	14:02	8.4	10.5 C	50.9 F	11.6	13.8 ntu	40	0	High water level.
			B	A		A	B	A	A	