

**Lodi Citizen's Monitoring - Lodi, California**

**November  
11/27/2012**

**RAINFALL: (New Season Begins- 7-01-12)**

**Season total: 3.24 " inches**

**Last rain: TODAY! - .76"**

**Weather: Avg. temp.( 16.5C/61.6F)- calm, overcast, cloudy**

**VISUAL OBSERVATIONS**

**RAIN EVENT IN LAST 24 HRS.**

DATE	SITE	ODOR	ALGAE	FOAM	TURBID.	FLOW	OIL	LITTER	COLOR
27-Nov-12	site 1	None	none	None	Clear	Low	None	Mod(6-10 pcs)	Brown
	site 2	None	none	None	Clear	Low	None	Mod(6-10 pcs)	Green
	site 5								
	site 7	None	None	None	Clear	Low	None	None	None
	site 7A								
	site 8	None	None	None	Clear	None	None	light(<5%)	None
	site 9	None	None	None	Clear	Low	None	None	None
	site 9A								

**River Water Level: WID - Lodi Lake empounded 2-24-12. Camanche releases- 411 cfs. / Pardee 1031 cfs.**

- Monitors:** Sites # 1 Vacarezza Private Property- (Lodi Academy- Hall) T. Katzakian, A. Wilson, T. deSousa,  
 Site # 2- Casa de Lodi- Gritsch Private Property- same as site 1  
 Site # 5- 1050 N Lincoln  
 Sites # 7- Lodi Lake Park- Near Gazebo- (Tokay- Juran)- D. Schatz, B. Price, G. Bedi, J. Hood  
 Site # 7-A- East end (S/o SD) Lake-  
 Site # 8- West side Lodi Lake, near outfall- from the boat- (Tokay- Starr)- M. Netto, M. Batth, D. Boyle, B. Healy  
 Site # 9- Above WID Bridge and Dam- from the boat (Starr)- same as site 8  
 Site # 9-A- Below Bridge-

Test Site	Date	Time	pH	Water Temperature		Dissolved Oxygen mg/L	Turbidity NTU	EC Conduct. uS	Nitrate, as mg/L Nitrogen	Remarks
				C	F					
Site #1 River before City Storm System inlets	11/27/12	14:48	9.3 D	13.1 C A	55.6 F	9.7 A	1.2 ntu A	40 A	0 A	lots of jumping fish, leaf litter
Site # 2 River near Casa de Lodi	11/27/12	15:10	7.8 A	13.0 C A	55.4 F	9.6 A	2.1 ntu A	40 A	0	leaf litter
Site # 5 River at 1050 N Lincoln					32.0 F					
Site # 7 River, near Gazebo N/O Lodi Lake	11/27/12	15:30	7.8 A	13.0 C A	55.4 F	8.9 A	2.1 ntu A	50 A	0 A	a dog was in the water
Site # 7A East end (S/o SD) Lodi Lake					32.0 F					
Site # 8 Lodi Lake Near Storm Drain	11/27/12	15:39	7.9 A	15.4 C B	59.7 F	8.68 B	2.5 ntu A	40 A	0 A	on the boat, water is clear.
Site # 9 River- Upstream of dam					32.0 F					
Site # 9A River below WID under bridge	11/27/12	15:21	7.7 A	15.0 C A	59.0 F	9.5 A	1.7 ntu A	50 A	0 A	on the boat, near the dam.