

<b>Lodi Citizen's Monitoring - Lodi, California</b>						<b>RAINFALL: (New Season Begins- 7-01-12)</b>			
<b>JUNE</b>						<b>Season total:</b>		<b>13.81"</b>	
<b>6/19/2013</b>						<b>Last rain:</b>		<b>7-Apr .05"</b>	
<b>Weather: Avg. temp. (24.9 C/76.82 F)</b>									
<b>VISUAL OBSERVATIONS- Calm, clear and sunny. Some breeze at sites 7 and 8.</b>									
DATE	SITE	ODOR	ALGAE	FOAM	TURBID.	FLOW	OIL	LITTER	COLOR
<b>19-Jun-13</b>	site 1	None	None	None	Clear	Low	None	None	None
	site 2	None	None	None	Clear	Low	None	None	None
	site 5								
	site 7	None	None	None	Clear	Med.	None	None	None
	site 7A								
	site 8	Musty	None	None	Murky	Low	None	Mod(6-10 pcs)	None
	site 9	None	None	None	Clear	Low	None	Light (<5pcs.)	None
	site 9A								
<b>River Water Level: WID - Lodi Lake empounded. 2-21-13. Camanche releases- 275 cfs. / Pardee 365 cfs.</b>									
<b>Monitoring Team</b>									
Sites # 1 Vacarezza Private Property- Tokay High- D. and A. Castelanelli									
<b>Lodi and Tokay</b>	Site # 2- Casa de Lodi- Gritsch Private Property- same as site # 1.								
<b>Summer Team</b>	Site # 5- 1050 N Lincoln								
	Sites # 7- Lodi Lake Park- Near Gazebo- Lodi High -(Turner)- Z. Baig, Z. Ghadialy, P. Dhillon, D. Lund.								
	Site # 7-A- East end (S/o SD) Lake-								
	Site # 8- West side Lodi Lake, near outfall- at shore- Lodi High (Turner) same as site 7								
	Site # 9- Above WID Bridge and Dam-								
	Site # 9-A- Below Bridge- Tokay HS- J. Hood, F. Huang								

Test Site	Date	Time	pH	Water Temperature		Dissolved Oxygen mg/L	Turbidity NTU	EC Conduct. uS	Nitrate, as mg/L Nitrogen	Remarks
Site #1 River before City Storm System inlets	6/19/13	11:41	7.7 A A	17.6 C A	63.7 F A	4.9 F CHEMET 8	1.8 ntu A	50 A	0 A	DO probe broken. kayakers, little fish, dead plants in water.
Site # 2 River near Casa de Lodi	6/19/13	11:57	7.7 A A	18.2 C A	64.8 F A	5.4 F CHEM 9	1.3 ntu A	40 A	0 A	sunny- no shade. No plant life in water.
Site # 5 River at 1050 N Lincoln										
Site # 7 River, near Gazebo N/O Lodi Lake	6/19/13	12:50	7.8 A A	21.6 C A	70.9 F A	9.8 A	2.1 ntu A	50 A	0 A	Boats passing, person is fishing near site.
Site # 7 River, near Gazebo N/O Lodi Lake										
Site # 8 Lodi Lake Near Storm Drain	6/19/13	11:51	7.8 A A	22.4 C A	72.3 F A	8.80 A 102.1%	2.3 ntu B	70 A	0 A	Dogs playing in water. Construction on the other side of levee.
Site # 9 River- Upstream of dam										
Site # 9A River below WID below bridge	6/19/13	11:42	7.8 A A	24.0 C A	75.2 F	8.6 A	1.11 ntu A	40 A	0 A	3 fisherman